



OJ ELECTRONICS

WIRING DIAGRAM WLM2-1BA



THERMAL ACTUATORS

OUTPUT 1	OUTPUT 2	OUTPUT 3	OUTPUT 4	OUTPUT 5	OUTPUT 6	OUTPUT 7	OUTPUT 8	OUTPUT 9	OUTPUT 10	OUTPUT 11	OUTPUT 12	OUTPUT 13	OUTPUT 14	OUTPUT 15	OUTPUT 16
L	N	L	N	L	N	L	N	L	N	L	N	L	N	L	N
31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46

THERMAL ACTUATORS

OUTPUT 1	OUTPUT 2	OUTPUT 3	OUTPUT 4	OUTPUT 5	OUTPUT 6	OUTPUT 7	OUTPUT 8	OUTPUT 9	OUTPUT 10	OUTPUT 11	OUTPUT 12	OUTPUT 13	OUTPUT 14	OUTPUT 15	OUTPUT 16
L	N	L	N	L	N	L	N	L	N	L	N	L	N	L	N

SENSOR CONTROLLER

DISJAY	SENSOR	+	+	+	+	+	+
47	48	49	50	51	52	53	54

SENSOR CONTROLLER

1	Q	App	+	+	+	+	+
17	18	19	20	21	22	24	25

